

## Station checklist

### PTS 3 combine set

No.	Item	Quantity	Serial No.
1	PTS3-V-U-AJM-UCM-SD-1000-XY-TB	1	
	WHITE BASE PLATE	1	
	EXTENSION PLUG	1	
	VT-4SIDE-670-INNER-ADJUSTMENT-SLIDER	1	
	PTS-UCM-V3	1	
	M6-80&85	1	
	CM-328-SLIDER-COMBINE BRACKET	1	
	XY Table	1	
	SD-1000-D1-PTS - ANALOG CONTROLLER	1	CAFZ17725
	POWER CABLE (1VS)	1	
	POWER SUPPLY 24V : 2.7A	1	
	POWER CORD - UK/US/EU (1.8 Meter)	1	
	EXT-24V-F-3M - EXTENSION CABLE	1	
	FLEXIBLE ARM & LPR-057-065092-01	1	
	ROTATE BRACKET BARLIGHT	2	
	ALLEN KEY	1	
	ROTATE CAMERA BRACKET	1	
	SCREW BOX	1	



**CLM2**

No.	Item	Quantity	Serial No.
2	DK-CLM2-AJM-UCM-U-CP-LP	1	-
	PTS-UCM-V3	1	-
	M6-80&85	1	-
	VT-4SIDE-ADJUSTMENT-CLM-350MM	1	-
	SCREW BOX	1	-
	LPR-057-065092-01	1	-
	CAMERA PLATE	1	-
	JIG-BASE-03	1	-
	CM-328-SLIDER- COMBINE BRACKET	1	-







































